

PERFUM 3 Version Control

- October 1, 2021: Fixed bug that resulted in the BPIP algorithm not being called when using AERMOD.
- June 30, 2020: Fixed bug that resulted in correct air concentrations in output file when multiple application rates are specified.
- March 2, 2020: Changed parameter bound error to warnings for stack height, stack diameter, exit velocity, exit temperature, air diffusion rate, and water diffusion rate.
- February 18, 2020: Fixed bug to allow smaller exit velocity values in the GUI and changed parameter bounds for exit velocity.